Test Report issued under the responsibility of:





IEC 60 47-200 Control of the control

Report Number.....: 00901-CB2018CQC-083290

Date of issue....: 2019-01-30

Total number of pages 19

Name of Testing Laboratory Shanghai Testing & Inspection Institute for Electrical Equipment

TEST REP

preparing the Report: (STIEE)

Applicant's name: Zhejiang Tengen Electric Co.,Ltd.

Address : Sulv Industrial Area, Liushi Town, Yueqing City, Zhejiang Province,

P.R.China

Test specification:

Standard: IEC 60947-2:2016

Test procedure: CB Scheme

Non-standard test method: N/A

Test Report Form No.: IEC60947_2H

Test Report Form(s) Originator....: DEKRA Certification B.V.

Master TRF: Dated 2017-04

Copyright © 2017 IEC System of Conformity Assessment Schemes for Electrotechnical Equipment and Components (IECEE System). All rights reserved.

This publication may be reproduced in whole or in part for non-commercial purposes as long as the IECEE is acknowledged as copyright owner and source of the material. IECEE takes no responsibility for and will not assume liability for damages resulting from the reader's interpretation of the reproduced material due to its placement and context.

If this Test Report Form is used by non-IECEE members, the IECEE/IEC logo and the reference to the CB Scheme procedure shall be removed.

This report is not valid as a CB Test Report unless signed by an approved CB Testing Laboratory and appended to a CB Test Certificate issued by an NCB in accordance with IECEE 02.

General disclaimer:

The test results presented in this report relate only to the object tested.

This report shall not be reproduced, except in full, without the written approval of the Issuing CB Testing Laboratory. The authenticity of this Test Report and its contents can be verified by contacting the NCB, responsible for this Test Report.

Test item description...... Moulded case circuit breaker

Trade Mark..... | TENGEN

Sulv Industrial Area, Liushi Town, Yueging City, Zhejiang

Province, P.R.China

Model/Type reference TGM3E-250M,TGM3E-250H

Page 2 of 19 Report No. 00901-CB2018CQC-083290

Ratings			
Responsible Testing Laboratory (as applicable), testing procedure and testing location(s):			
X	CB Testing Laboratory:	Shanghai Testing & Inspection Institute for Electrical Equipment (STIEE)	
Testing location/ address:		505 Wu Ning Rd. Shanghai 200063, P.R. CHINA	
Tested by (name, function, signature):		Cui Tao/Engineer	流游
Аррі	roved by (name, function, signature):	Wei Qingyuan/ Senior Engineer	魏水媛
	Testing procedure: CTF Stage 1:		
rest	ing location/ address:		
Tested by (name, function, signature):			
Approved by (name, function, signature):			
Testing procedure: CTF Stage 2:			
Testing location/ address:			
Tested by (name + signature):			
Witnessed by (name, function, signature) .:			
Approved by (name, function, signature):			
	Testing procedure: CTF Stage 3:		
	Testing procedure: CTF Stage 4:		
Testing location/ address:			
Tested by (name, function, signature):			
Witnessed by (name, function, signature) .:			
Approved by (name, function, signature):			
Supervised by (name, function, signature) :			